# 15 St. Stephens Street

## **Material information**

15 St. Stephens Street Tonbridge, TN9 2AB Kotini has gathered this property information and the sellers have confirmed it to be accurate as of: **14/06/2024 18:55** 



# Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive summary of the property you've requested to view to help inform your purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.

		•
		-
U		_
	ш	

# Contents

Additional information Alterations & changes Boundaries Completion & moving Connectivity Council tax **Delay factors** Displutes & complaints Electricity **Electrical works Energy efficiency Environmental issues** Guarantees, warranties, and indemnity insurances Heating Insurance Listing & conservation Notices Other issues Ownership Parking **Rights and informal arrangements** Sellers capacity Services crossing the property **Specialist issues** Type of construction Water & drainage



# **Additional information**

#### Non-compliant with restrictions on use and alterations

No

#### Other material issues

No

#### Other charges not mentioned elsewhere

No



# Alterations & changes

### Planning permission breaches

No

**Unfinished works at the property** No

**Unresolved planning issues** No

### Structural alterations

**Structural alterations made to the property** No

### $\checkmark$ Change of use

**Property subject to a change of use** No

### ↓ Windows, roof windows, roof lights or glazed doors installations

**Details of the windows, roof windows, roof lights or glazed doors installation** All four windows and their frames replaced with UPVC double glazed ones.

**Planning permission obtained for the windows, roof windows, roof lights or glazed doors** Not required

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002 Yes

#### Details why planning permission approval wasn't obtained

The windows were installed prior to my purchase of the property in May 2014, but I assume the work was done under permitted development.

#### Details why deed restriction consent wasn"t obtained

I can only assume that this was not required.

#### **Deed restriction consent obtained for the windows, roof windows, roof lights or glazed doors** Not required

Details why listed building consent wasn"t obtained

The property is not a listed property.

**Building regulation approval obtained for the windows, roof windows, roof lights or glazed doors** Yes

Listed building consent obtained for the windows, roof windows, roof lights or glazed doors Not required

### ↓ Conservatories

#### Conservatory added to the property

No



Boundaries
<b>Boundaries are uniform</b> Yes
<b>Property boundaries differ from the title plan</b> No
<b>Boundaries have been moved</b> No
<b>Proposal to alter the boundaries</b> No
<b>Part of the property are outside the legal ownership of the seller</b> Yes
<b>Part of the property on separate deed</b> No
<b>Details of the parts of the property outside the sellers legal ownership</b> The accessway between the property and the neighbouring property (number 17) is not owned by any of the residents that have a right of access to use it.
<b>Adjacent land included in the sale</b> No

Flying freehold at the property

No

# $\checkmark$ Boundary ownership

#### Left boundary

Seller

Rear boundary

Neighbour

#### **Right boundary**

Neighbour

#### Front boundary

Seller



# **Completion & moving**

<b>Seller will remove any rubbish</b> True	
<b>Seller will replace any light fittings</b> True	
<b>Seller will take reasonable care</b> True	
<b>Seller will leave all keys</b> True	
<b>Property in a chain</b> No	
<b>Any dates the seller can't move on</b> No	
Sale price sufficient to settle the mortgage No mortgage	

# Connectivity

↓ Telephone

**Telephone line connected to the property** No

### $\downarrow$ Cable & TV

Cable or satellite TV connected to the property  $\ensuremath{\mathsf{No}}$ 

### ↓ Broadband

**Broadband connection at the property** FTTP (Fibre to the Premises)

### ↓ Mobile coverage

Mobile signal issues at the property No





#### **Council Tax band**

В

### Alterations affecting Council Tax band

No

#### Annual Council Tax

1749.6



# **Delay factors**

Potential delays to the transaction

No



# **Disputes & complaints**

Past disputes and complaints

No

Potential disputes and complaints No

110



# Electricity

↓ Mains electricity

**Electricity meter location** In the alcove cupboard in the living room.

Mains electricity supplier Octopus Energy

Property connected to mains electricity

Yes

## eq Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property No

### $\checkmark$ Other electricity sources

Other sources of electricity connected to the property No



Electrical works	
Electrics tested by a qualified electrician No	
Year the electrical work was carried out 2023	
<b>Details of the electrical work</b> Installation of a new bathroom extractor fan and ducting	
<b>Any electrical works at the property since 2005</b> Yes	



# **Energy efficiency**

#### **Current EPC rating**

D

### Green deal loan in place

No



# **Environmental issues**

### $\checkmark$ Flooding

#### Property flooded before

No

#### Property at risk of flooding

No

### ↓ Radon

# Radon test carried out

No

#### Radon remedial measures on construction

No

### $\downarrow$ Coal mining

#### Coal mining risk

No

## $\checkmark$ Other mining

#### Other mining risk

No

### $\downarrow$ Coastal erosion

# Coastal erosion risk

No

### ↓ Other

#### Other environmental risks

No



# Guarantees, warranties, and indemnity insurances

<b>Guarantees or warranties available for the property</b> Yes
<b>New home warranty</b> No
<b>Guarantes or warranties for roofing work</b> No
<b>Guarantes or warranties for damp proofing treatment</b> No
<b>Guarantes or warranties for central heating and/or plumbing</b> No
<b>Guarantes or warranties for double glazing</b> Yes
Guarantes or warranties for electrical repair or installation No
<b>Guarantes or warranties for subsidence work</b> No

#### Guarantes or warranties for solar panels

No

#### Outstanding claims or applications against the guarantees or warranties

No

#### Title defect insurance in place

Yes

#### Details of the title defect insurance

I have an indemnity policy from Legal & Contingency to protect me from future claims in respect of chancel repair liability. This was a one-off payment of £15 and has no expiry date.

#### Any other guarantees or warranties

No

#### Guarantes or warranties for timber rot infestation treatment

No



# Heating

**Type of heating system** Central heating

**Central heating fuel** Mains gas

**Mains gas, Oil or LPG supplier** Octopus Energy

Date of installation 2016-06-23

Date of the last service or maintenance 2023-09-15

Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010?

Yes

**Location of the gas meter** Outside the front of the property.

**Is the heating system in good working order** Yes

#### Other heating features at the property

Double glazing



# Insurance

#### **Property insured**

Yes

↓ Insurance concerns		
<b>Insurance previously refused</b> No		
<b>Insurance subject to high excesses</b> No		
<b>Insurance subject to unusual conditions</b> No		
<b>Past insurance claims</b> No		
<b>Abnormal rise in insurance premiums</b> No		
End of section		



# Listing & conservation

### $\downarrow$ Listing status

#### Listed building in England or Wales

No

## $\checkmark$ Conservation

Located in a designated conservation area No

### ↓ Tree Preservation

**Tree preservation order in place** No

•	

# **Notices**

#### Planning application notice(s) No

Required maintenance notice(s) No

Neighbour development notice(s) No

Listed building application notice(s)

No

Infrastructure project notice(s) No

Party wall act notice(s)

No

#### Other notices

No



Other issues	
Excessive noise issues	
No	
Crime issues	
No	
Occupied by someone under caution or conviction	
No	
Failed transactions in last 12 months	
No	



# **Ownership - 1**

Title number

K536092

**Tenure of the property** Freehold

#### Whole freehold being sold

Yes





**Type of parking available** On Street

Disabled parking available Yes Controlled parking in place Yes Electrical vehicle charging point at the property No

# **Rights and informal arrangements**

#### Shared contributions

No

#### Neighbouring land rights

Yes

#### Details of neighbouring land rights

The accessway between the property and neighbouring property (number 17) isn't owned by any of the residents surrounding it, but we have access rights to it. There are no costs associated with using the accessway.

#### Public right of way

Yes

#### Details of public right of way

The occupant of the adjoining property (number 13) has a right of way across the patio. This is only used for taking out/in bins.

#### **Rights of light**

No

#### **Rights of support**

No

**Rights created through custom** 

No

#### Rights to take from land

No

#### Mines and minerals under the property

No

#### Church chancel liability

Yes

#### Details of church chancel liability

The property lies within a tithe district with a potential risk of chancel repair liability. When I purchased the property in May 2014, my solicitor took out an indemnity policy, which was a one-off purchase of £15 (the policy has no expiry date).

#### Other rights

No

#### Attempts to restrict access

No

# **Sellers capacity**

**Capacity** Legal Owner



# Services crossing the property

Pipes, wires, cables, drains coming to property

Yes

#### Details of pipes, wires, cables, drains coming to property

The sewer is under the accessway between the property and neighbouring property (number 17). There is an access panel in the accessway.

#### Pipes, wires, cables, drains from property

Yes

#### Details of pipes, wires, cables, drains from property

There is a waste water pipe underneath the patio area of the property (at a depth of approx 3 feet) that is connected to the attached property (number 13).

#### Formal or informal agreements for services crossing the property

No



# **Specialist issues**

#### Property treated for dry rot, wet rot or damp

Yes

#### Details of treatment for dry rot, wet rot or damp

In April 2023, five subfloor air vents were installed to the front and side of the property to address a minor occurrence of rising damp on the external wall of the living room.

#### Japanese knotweed at the property or neighbouring land

No

#### Subsidence or structural faults

No

#### Ongoing health or safety issues at the property

No

#### Asbestos at the property

No



# Type of construction

Property is built with standard forms of construction

Yes

**Spray foam installed at the property** No

Details of any accessibility adaptations at the property

No accessibility adaptations

### ↓ Building safety

Building safety issues at the property No

# Water & drainage

↓ Water

Mains water connected to the property

Yes

Mains water supplier South East Water

Mains water supply metered No

**Location of the stopcock** Under the sink in the kitchen.

### ↓ Drainage

Mains foul drainage connected to the property Yes

Mains foul drainage supplier South East Water (collect on behalf of Southern Water).

Surface water drainage connected to the property

Yes

Maintenance agreements in place for the drainage system

No